

VANDERVEEN-TRANS-PP80 corrections. Vs. May-2023

[See *audioXpress* May-2023 pp. 21-28]

The listing below shows corrections on our audioXpress VDV-T-PP80 article.
If you find other items, please be so kind to warn us at: info@mennovanderveen.nl

- 1) **R12 is wrongly indicated ONLY on the driver-PCB.** There its value reads 47kOhm. The correct value is: **R12 = 41k2**. In all circuit diagrams and the BOM this value is mentioned correctly.
- 2) **The START-UP procedure contains a mistake in step-5.** The correct version is:
 5. Check on the driver-PCB **on opamps-1 and -2** at their opamp-outputs (pin-1 and pin-7) to read less than 5 mVdc with reference to ground.
- 3)
- 4)
- 5)